

Aftermarket Support OBSOLESCENCE T155 Card Replacement


Do you run a Goss or WISPRINT web press system?

Are you experiencing remote registration problems due to T155 electronic card issues?

We now have an upgrade to replace the functionality of the now obsolete T155 cards

T155 REPLACEMENT

T155 electronic cards are an integral part of the remote registration system and were used for many years on Goss and Wisprint presses. These cards are now obsolete and can no longer be manufactured due to the discontinuation of the required parts. To support our customers through this obsolescence, GGSC has developed an upgrade to replace the functionality of these cards and restore the full operation of the remote registration system.




The T155 card replacement upgrade replaces all the functionality of the T155 cards and allows remote control of lateral and circumferential registration from a newly supplied console. The console includes a laydown area for the sheets as well a touchscreen and a keypad, either of which can be used to make register movements.

After the upgrade, the existing console remains and is used to control other press functions, while the new console would be used for registration moves only.

INCLUDED

- ✓ New console with sheet laydown area, touchscreen and register keypad
- ✓ VPN for remote service and diagnostics, if required
- ✓ All wiring [must be cut to length and terminated on site]
- ✓ Complete set of schematics and installation instructions



Installation is straightforward and can be completed by customer maintenance personnel or local electricians. Alternatively, installation is available from GGSC personnel or one of our certified representatives; quotes available on request.

Are you ready to get started?

Please contact the aftermarket team today



sales@goss-china.com



www.wisprinteurope.com